

HARVEY DONALDSON & GIBSON

CHARTERED SURVEYORS

Parent to HomeReportScotland.scot







- 1. Single Survey
- 2. Energy Report
- 3. Property Questionnaire



survey report on:

Property address	18B Hillhead, Coylton, Ayr, KA6 6JR	
Customer	Executor of Mrs A Cowan	
, 		
Customer address	24 Shaw Place, Coylton, KA6 6QF	
Prepared by	Harvey Donaldson and Gibson	
Date of inspection	8th June 2022	



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The ultimate holding company of Harvey Donaldson & Gibson is Countrywide plc. In Scotland, Countrywide plc also own Slater Hogg & Howison and Countrywide North. A full list of estate agents owned or under franchise to Countrywide plc is available on request. Harvey Donaldson & Gibson trades as an entirely separate company and has no financial interest whatsoever in the disposal of the property being inspected.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information

contained in the Report and the generic Mortgage Valuation Report.²

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be

researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The subjects comprise a detached bungalow.
Accommodation	Ground Floor: Entrance vestibule, hallway, living/dining room, two bedrooms, kitchen, bathroom, en-suite shower room and conservatory.
Gross internal floor area (m²)	93 approx. (85 approx. excluding the conservatory)
Neighbourhood and location	The property is situated in a residential area developed with properties of varying age and style within the village of Coylton. There is farmland to the rear. Local amenities are available in a reasonable distance.
Age	18 years approx.
Weather	Overcast with showers.
Chimney stacks	None.
Roofing including roof space	The roof structure is pitched, timber supported and covered with concrete tiles. The roof space is insulated at ceiling joist level and partly floored.
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate. The rainwater fittings are plastic components.

Main walls	Visually inspected with the aid of binoculars where
	appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The main walls are of modern timber framed cavity construction finished externally with facing brick and render.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	The windows and doors are uPVC framed double glazed units. The soffit and fascia boards are uPVC.
External decorations	Not applicable.
Conservatories / porches	Visually inspected.
	The conservatory is of uPVC framed double glazed construction. The roof is pitched and covered with polycarbonate sheeting.
Communal areas	None
Garages and permanent outbuildings	Visually inspected.
	There is a single car garage of rendered blockwork construction with a pitched roof covered with concrete tiles.
Outside areas and boundaries	Visually inspected.
	There are garden grounds to the front, side and rear elevations. There is a chipped driveway. Boundaries are formed by masonry walls and fences.
Ceilings	Visually inspected from floor level.
	The ceilings are of plasterboard construction.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	The internal walls are of timber framed construction lined with plasterboard.
Floors including sub floors	The floors are of solid construction. All floors were covered with fixed coverings.

Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	The internal doors are moulded and glazed timber units. The skirtings and door surrounds are moulded. The kitchen is fitted with a range of wall and base units.
Chimney breasts and fireplaces	Visually inspected.
	No testing of the flues or fittings was carried out.
	There are no chimney breasts. There is a decorative fireplace within the living room.
Internal decorations	Visually inspected.
	Papered and painted finishes have been applied.
Cellars	None.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. A main supply is connected. The meter and consumer unit are located within the hall cupboard.
Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. A main supply is connected. The meter is located in an external meter box.
Water plumbing both some fittings	
Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	The visible pipes are of copper and plastic materials.
	The bathroom contains a four piece white suite.
	The en-suite shower room contains a three piece white suite.

Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	Central heating is by way of a gas fired combination boiler located in the kitchen. This supplies a system of hot water radiators and also provides domestic hot water to taps.
Drainage	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.
	The property is believed to be connected to mains drainage.
Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	The property has smoke detectors.
	Scottish government regulations came into effect on 1st February 2022, which requires each property to have linked smoke and heat detectors and if gas/carbon burning appliances are present then a carbon monoxide alarm fitted. Upgrading may be required to comply with these regulations. Purchasers should satisfy themselves with regards to compliance.

Any additional limits to inspection

For flats / maisonettes

Only the subject flat and internal communal areas giving access to the flat were inspected.

If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.

The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.


The property was vacant, furnished with fitted floor coverings in all rooms.

Our inspection of the roof space was restricted by insulation materials and boardings.

This report does not constitute a full and detailed description of the property and a structural investigation was not carried out. No inspection was undertaken of woodwork or other parts of the structure which are covered, unexposed or otherwise inaccessible and as a result no guarantee can be given that such parts of the structure are free from rot, beetle or other defects.

It was dry on the date of inspection. Leakage and water penetration within roof spaces, around chimney breasts, window openings, etc are sometimes only visible during or immediately after, adverse weather conditions.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1) Chimney pots
- 2) Coping stone
- 3) Chimney head
- 4 Flashing
- 5 Ridge ventilation
- 6 Ridge board
- 7) Slates / tiles
- 8 Valley guttering
- 9 Dormer projection
- 10) Dormer flashing
- 11) Dormer cheeks
- (12) Sarking
- (13) Roof felt
- (14) Trusses
- (15) Collar
- 16 Insulation
- (17) Parapet gutter
- (18) Eaves guttering
- Rainwater downpipe
- 20) Verge boards /skews
- 21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- 24) Chimney breast
- 25) Window pointing
- 6 Window sills
- 27) Rendering
- (28) Brickwork / pointing
- 29) Bay window projection
- 30 Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- 33) Damp proof course
- 34) Base course
- 35) Foundations
- 36) Solum
- Floor joists
- 38) Floorboards
- 39) Water tank
- Hot water tank

2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category	1
Notes	No visible evidence of significant structural movement was noted within the limitations of the inspection. All buildings move seasonally as a result of external factors such as gravity, temperature, moisture content and vibrations. Consequently most buildings will have some minor cracks related to these factors. Minor cracks can be filled but often recur seasonally due to normal movement in a building.

Dampness, rot and infestation	
Repair category	1
Notes	None noted within the limitations of the inspection.

Chimney stacks	
Repair category	-
Notes	Not applicable.

Roofing including roof space	
Repair category	1
Notes	No obvious significant defects were noted to the roof structure or coverings, within the limitations of the inspection.

Rainwater fittings	
Repair category	1
Notes	No obvious significant defects were noted to the rainwater fittings. Localised vegetation was noted within the gutters. This should be cleared during routine maintenance. It was not raining at the time of the inspection and it is therefore not possible to confirm that all joints are completely water tight.

Main walls	
Repair category	1
Notes	No obvious significant defects were noted to the main wall surfaces.

Windows, external doors and joinery	
Repair category	1
Notes	No obvious significant defects were noted to the windows, doors or other external joinery fixtures.

External decorations	
Repair category	-
Notes	Not applicable.

Conservatories/porches	
Repair category	2
Notes	The conservatory appears to be in reasonable order for age and type, however, one of the double glazed units has failed with condensation noted between the panes.

Communal areas	
Repair category	-
Notes	Not applicable.

Garages and permanent outbuildings	
Repair category	1
Notes	The garage appears to be in reasonable order allowing for age and type. There is localised timber decay to the side door frame.

Outside areas and boundaries	
Repair category	2
Notes	The outside areas appear to be in reasonable condition for age and type. Some deterioration was noted to garden/boundary wall render, fences and access steps (frost damage).

Ceilings	
Repair category	1
Notes	No obvious significant defects were noted to the ceilings.

Internal walls	
Repair category	1
Notes	No obvious significant defects were noted to the internal walls.

Floors including sub-floors	
Repair category	1
Notes	No obvious significant defects were noted to the floors, within the limitations of the inspection.

Internal joinery and kitchen fittings	
Repair category	1
Notes	No obvious significant defects were noted to the internal joinery fixtures or kitchen fittings allowing for normal wear and tear.

Chimney breasts and fireplaces	
Repair category	1
Notes	No obvious significant defects were noted.

Internal decorations	
Repair category	1
Notes	No obvious significant defects were noted to the internal decorations.

Cellars	
Repair category	-
Notes	Not applicable.

Electricity	
Repair category	1
Notes	No obvious significant defects were noted, however, only the most recently constructed or re-wired properties have installations which fully comply with current regulations. It is good practice to have electrical systems fully tested upon a change in ownership, where upgrading may be identified by the contractor.

Gas	
Repair category	1
Notes	It is recommended good practice that all gas installations should be checked periodically. This should be regarded as a routine safety and maintenance check.

► Water, plumbing and	d bathroom fittings
Repair category	1
Notes	No obvious significant defects were noted to the accessible plumbing fixtures or sanitary fittings.

Heating and hot wat	er
Repair category	1
Notes	The system was not running at the time of inspection but appeared serviceable. It is recommended good practice that gas boilers are serviced on an annual basis by an appropriately qualified person. The boiler's service history should be checked by referring to the service records. If there is no record of a recent service, the boiler should be checked by an appropriately qualified person.

Drainage	
Repair category	1
Notes	No obvious significant defects were noted to the drainage system, within the limitations of the inspection.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	-
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	-
Conservatories/porches	2
Communal areas	-
Garages and permanent outbuildings	1
Outside areas and boundaries	2
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	-
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground
2. Are there three steps or fewer to a main entrance door of the property?	Yes X No
3. Is there a lift to the main entrance door of the property?	Yes No X
4. Are all door openings greater than 750mm?	Yes No X
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No
6. Is there a toilet on the same level as a bedroom?	Yes X No
7. Are all rooms on the same level with no internal steps or stairs?	Yes X No
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

The tenure is understood to be outright ownership.

Scottish government regulations came into effect on 1st February 2022, which requires each property to have linked smoke and heat detectors and if gas/carbon burning appliances are present then a carbon monoxide alarm fitted. Upgrading may be required to comply with these regulations. Purchasers should satisfy themselves with regards to compliance.

In line with our normal practice, it is specifically assumed that the property and its value are unaffected by any matters which would or should be revealed to a competent Completing Solicitor by a local search and replies to the usual enquiries, or by any statutory notice and planning proposal.

Estimated reinstatement cost for insurance purposes

£225,000 (Two hundred and twenty five thousand pounds sterling).

Valuation and market comments

In its present condition the opinion of valuation for the Outright Ownership interest with vacant possession on the 8th June 2022 is £180,000 (One hundred and eighty thousand pounds sterling).

Signed	Security Print Code [456853 = 5696] Electronically signed
Report author	Thomas O'Kane
Company name	Harvey Donaldson and Gibson
Address	Room E101, Floor E, Marathon House, Olympic Business Centre, Kilmarnock, Ayrshire, KA2 9BE



18B Hillhead, Coylton, Ayr, KA6 6JR Executor of Mrs A Cowan 8th June 2022
X House Bungalow Purpose built maisonette Converted maisonette Purpose built flat Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks)
X Detached Semi detached Mid terrace End terrace Back to back High rise block Low rise block Other (specify in General Remarks)
lieve that the property was built for the public sector, Yes X No illitary, police?
y Floor(s) on which located No. of floors in block Lift provided? Yes No
No. of units in block Construction
Leasehold Ground rent £ Unexpired years
1 Living room(s) 2 Bedroom(s) 1 Kitchen(s) 2 Bathroom(s) 2 WC(s) 1 Other (Specify in General remarks)
cluding garages and outbuildings) 93 m² (Internal) 107 m² (External)
greater than 40%) X Yes No
Outbuildings
□ Double garage □ Parking space □ No garage / garage space / parking space X Yes □ No
gs:

Construction							
Walls	Brick	Stone	Concrete	X Timber frame	Othe	r (specify in Gen	eral Remarks)
Roof	X Tile	Slate	Asphalt	Felt	Othe	r (specify in Gen	eral Remarks)
Special Risks							
Has the property s	suffered struc	ctural moveme	ent?			Yes	X No
If Yes, is this rece	nt or progres	sive?				Yes	No
Is there evidence, immediate vicinity		eason to antic	ipate subsidenc	e, heave, landslip	or flood in the	Yes	X No
If Yes to any of the	e above, prov	vide details in	General Remar	ks.			
Service Connec	tion						
	nspection onl		ces appear to be	e non-mains, pleas	se comment o	on the type a	nd location
Drainage	X Mains	Private	None	Water	X Mains	Private	None
Electricity	X Mains	Private	None	Gas	X Mains	Private	None
Central Heating	X Yes	Partial	None		_	_	_
Brief description of	of Central Hea	ating:					
Full gas system.							
Site							
Apparent legal iss	ues to be ve	rified by the co	onveyancer. Ple	ase provide a brief	f description i	in General R	emarks.
Rights of way		ves / access		r amenities on separate	_	red service conr	
III-defined boundar	ies	Agricul	tural land included v	vith property	Othe	er (specify in Ge	neral Remarks)
Location							
Residential suburb	Re	esidential within to	own / city Mix	ed residential / comme	ercial Mair	nly commercial	
X Commuter village	Re	emote village	Iso	lated rural property	Othe	er (specify in Ge	neral Remarks)
Planning Issues	5						
Has the property b	oeen extende	ed / converted	/ altered?	Yes X No			
If Yes provide deta	ails in Genera	al Remarks.					
Roads							
X Made up road	Unmade roa	ad Partly	completed new roa	d Pedestrian a	access only	Adopted	Unadopted

When inspected, the general condition of the property appeared to be consistent with its age and type of
When inspected, the general condition of the property appeared to be consistent with its age and type of construction, however, some repair and maintenance issues have been highlighted.
Essential Repairs
None.

Comment on Mortgageal	bility	
The property affords adeq lender's criteria.	uate security for loan purposes based on the valuation figure, subject to in	ndividual
Valuations		
Market value in present con Market value on completion Insurance reinstatement val (to include the cost of total r Is a reinspection necessary	of essential repairs lue rebuilding, site clearance, professional fees, ancillary charges plus VAT)	£ 180,000 £ £ 225,000
Buy To Let Cases		
month Short Assured Tenar	ge of monthly rental income for the property assuming a letting on a 6 ncy basis? here there is a steady demand for rented accommodation of this type?	£ Yes No
Signed Surveyor's name Professional qualifications Company name	Security Print Code [456853 = 5696] Electronically signed by:- Thomas O'Kane MRICS Harvey Donaldson and Gibson	
Address	Room E101, Floor E, Marathon House, Olympic Business Centre, Kilma KA2 9BE	rnock, Ayrshire,
Telephone	01563 852477	
Fax	0203 880 9199	
Report date	9th June 2022	

Energy Performance Certificate (EPC)

Dwellings

Scotland

18B HILLHEAD, COYLTON, AYR, KA6 6JR

Dwelling type: Detached bungalow
Date of assessment: 08 June 2022
Date of certificate: 08 June 2022

Total floor area: 85 m²

Primary Energy Indicator: 175 kWh/m²/year

Reference number: 5812-2026-5000-0438-3202 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst

Main heating and fuel: Boiler and radiators, mains


gas

You can use this document to:

- . Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£1,869	See your recommendations
Over 3 years you could save*	£231	report for more information

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band C (75)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band C (74)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Low energy lighting	£60	£153.00
2 Solar water heating	£4,000 - £6,000	£81.00
3 Solar photovoltaic (PV) panels	£3,500 - £5,500	£1005.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Timber frame, as built, insulated (assumed)	★★★★☆	★★★★ ☆
Roof	Pitched, 270 mm loft insulation	★★★★☆	★★★★ ☆
Floor	Solid, insulated (assumed)	_	_
Windows	Fully double glazed	★★★★☆	★★★★ ☆
Main heating	Boiler and radiators, mains gas	★★★★☆	★★★★ ☆
Main heating controls	Programmer, room thermostat and TRVs	★★★★☆	★★★★ ☆
Secondary heating	None	_	_
Hot water	From main system	★★★★☆	★★★★ ☆
Lighting	Low energy lighting in 25% of fixed outlets	***	***

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 31 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 2.6 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.2 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£1,194 over 3 years	£1,212 over 3 years	
Hot water	£279 over 3 years	£198 over 3 years	You could
Lighting	£396 over 3 years	£228 over 3 years	save £231
Totals	£1,869	£1,638	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures		Indiantive and	Typical saving	Rating after improvement		
		indicative cost	Indicative cost per year		Environment	
1	Low energy lighting for all fixed outlets	£60	£51	C 76	C 76	
2	Solar water heating	£4,000 - £6,000	£27	C 78	C 78	
3	Solar photovoltaic panels, 2.5 kWp	£3,500 - £5,500	£335	B 88	B 87	

Choosing the right improvement package



For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Low energy lighting

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting).

2 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

3 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	6,600	N/A	N/A	N/A
Water heating (kWh per year)	2,151			

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Thomas O'Kane

Assessor membership number: EES/016098

Company name/trading name: Harvey Donaldson & Gibson Chartered Surveyors Address: Room E101 Marathon House Olympic Business Centre

Kilmarnock KA2 9BE

Phone number: 01563852477

Email address: frances.wilson@hdg.co.uk

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greeners cotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT





Property Address	18B Hillhead, Coylton, Ayr, South Ayrshire, KA6 6JR
Vendor(s)	Mr James Cowan
Completion Date of Property Questionnaire	
System Ref:	QT643415-1





Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1.	Length of ownership			
••	How long have you owned the property? 18 years 2 months			
2.	Council Tax			
۷.				
	Which Council Tax band is your property in?			
	A & B & C & D & E & F & G	<u> </u>	H	×
3.	Parking			
	What are the arrangements for parking at your property? Please tick all that apply?			
	Garage ♥ Allocated parking space ♦	Dr	riveway	
	Shared parking ⊗ On street ⊗	Resident	permit	×
	Metered parking 😵 Other (please specify):			
4.	Conservation area			
	Is your property in a designated Conservation Area (that is an area of		Yes	×
	special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?		No	
		Don'	t know	×
5.	Listed buildings			
	Is your property a Listed Building, or contained within one (that is a building		Yes	×
	recognised and approved as being of special architectural or historical interest)?		No	
6.	Alterations/additions/extensions	•		
	During your time in the property, have you carried out any structural alterations, additions or		Yes	8
a.	extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?		No	
(i)	If you have answered yes, please describe below the changes which you have made:			
	Did you obtain planning permission, building warrant, completion certificate and other			
(ii)	consents for this work?		Yes	
		<u> </u>		×
(iv)	If you have answered yes, the relevant documents will be needed by the purchaser and you s solicitor as soon as possible for checking. If you do not have the documents yourself, please no these documents and your solicitor or estate agent will arrange to obtain them:			your



6.	Alterations/additions/extensions	
	Have you had replacement windows, doors, patio doors or double glazing installed in your	Yes 😵
b.	property? If you have answered yes, please answer the three questions below	No 🕢
/:\	Were the replacements the same shape and type as the ones you	Yes 😵
(i)	replaced?	No 😣
(ii)	Did the work involve any changes to the window or door openings?	Yes 😵
(,		No 😵
	Please describe the changes made to the windows doors, or patio doors (with approximate dat completed):	es when the work was
(iii)	Please give any guarantees which you received for this work to your solicitor or estate agent	
7.	Central heating	
	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main	Yes 🗸
a.	rooms of the property —	No 😵
	the main living room, the bedroom(s), the hall and the bathroom).	Partial 🚫
	If you have answered yes or partial – what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air) Gas	
	If you have answered yes, please answer the three questions below	
(i)	When was your central heating system or partial central heating installed?	18 years and 2 months
	Do you have a maintenance contract for the central heating system?	Yes 🗸
(ii)		No 😵
(,	If you answered yes please give details of the company with whom you have a maintenance of	ontract
	Scottish gas	
(iii)	When was your maintenance contract last renewed? (Please provide the month and year)	
•	Energy Payformance Cartificate	
8.	Energy Performance Certificate Does your property have an Energy Performance Certificate which is less	V 🖎
	than 10 years old?	Yes 😵 No 🐼
9.	Issues that may have affected your property	1.0
	Has there been any storm, flood, fire, or other structural damage to your	Yes 😵
a.	property while you have owned it?	No 🤡
	If you have answered yes is the damage the subject of any outstanding	Yes 😵
	insurance claim?	No 🐼
L	Are you aware of the existence of asbestos in your property?	Yes 😵
b.		No 🤣
	If you have answered yes please give details:	
	If you have answered yes please give details:	



10.	Services				
	Please tick which services are connected	ed to your property	and give details of	the supplier	
	Service	Connected	Suppli	er	
	Gas or liquid petroleum gas		Scottish p	ower	
	Water mains or private water supply		Scottish w	vater	
a.	Electricity		Scottish p	ower	
	Mains drainage		Mains sev	vage	
	Telephone		British tele	ecom	
	Cable TV or satellite		Sky		
	Broadband		Sky		
h	Is there a septic tank at your property?			Yes 😵	
b.	If you have answered yes please answer the questions below			No 🤡	
	Do you have appropriate consents for the	ne discharge of yo	ur septic tank?	Yes 😵	
(i)				No 😵	
				Don't know 🔕	
	Do you have a maintenance contract fo	r your septic tank?		Yes 😵	
/::\	No ⊗				
(ii)	If you answered yes please give details of the company with whom you have a maintenance contract				
11.	Responsibilities for shared or comme	on areas			
	Are you aware of any responsibility to contribute to the cost of anything				
	used jointly, such as repair of a shared drive, private road, boundary, or garden area?			Yes 😵	
a.				Yes 😵 No 🕢	
u.	34.40		, boundary, or		
a.	If you answered yes please give details	, ,	, boundary, or	No 🕢	
a.		, ,	, boundary, or	No 🕢	
	If you answered yes please give details Are you aware of any responsibility to c	ontribute to the co	st of repair and	No 🕢	
- u.	If you answered yes please give details	ontribute to the co	st of repair and	No ⊘ Don't know ⊗	
b.	If you answered yes please give details Are you aware of any responsibility to c	ontribute to the co	st of repair and	No ♥ Don't know Yes No ♥	
	If you answered yes please give details Are you aware of any responsibility to c	ontribute to the co	st of repair and	No ⊘ Don't know ⊗ Yes ⊗ No ⊘	
	If you answered yes please give details Are you aware of any responsibility to comaintenance of the roof, common stairs	ontribute to the co	st of repair and	No ⊘ Don't know ⊗ Yes ⊗ No ⊘	
b.	If you answered yes please give details Are you aware of any responsibility to comaintenance of the roof, common stairv If you answered yes please give details No Has there been any major repair or repl	ontribute to the covell, or other comm	st of repair and non areas?	No ⊘ Don't know ⊗ Yes ⊗ No ⊘	
	If you answered yes please give details Are you aware of any responsibility to comaintenance of the roof, common stairv If you answered yes please give details No	ontribute to the covell, or other comm	st of repair and non areas?	No ODON'T know S Yes No ODON'T know S	
b.	If you answered yes please give details Are you aware of any responsibility to comaintenance of the roof, common stairs If you answered yes please give details No Has there been any major repair or repl during the time you have owned the buil	ontribute to the convell, or other commands	st of repair and non areas?	No ODON't know S Yes No ODON't know S Yes S	
b. c.	If you answered yes please give details Are you aware of any responsibility to comaintenance of the roof, common stairs If you answered yes please give details No Has there been any major repair or repl during the time you have owned the bui	ontribute to the convell, or other commands	st of repair and non areas?	No Don't know Yes No Don't know Yes No Ves No Ve	
b.	If you answered yes please give details Are you aware of any responsibility to comaintenance of the roof, common stairs If you answered yes please give details No Has there been any major repair or repl during the time you have owned the buil	ontribute to the convell, or other commands	st of repair and non areas?	No ODON'T know S Yes No ODON'T know S Yes No Ves No Ves S	



11.	Responsibilities for shared or common areas						
	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin, or to maintain their boundaries?	Yes 😵					
	property, for example to put out their rubbish biri, or to maintain their boundaries?	No 🤡					
e.	If you answered yes please give details						
	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately owned.)	Yes 😵					
f.		No 🔗					
	<u>If you answered yes</u> please give details						
12.	Charges associated with your property						
12.	Is there a factor or property manager for your property?	Yes 😵					
	is there a lactor or property manager for your property:	No 🕢					
a.	If you answered yes please provide name and address and give details relating to deposits held						
	<u>II you answered yes</u> please provide name and address and give details relating to deposits field and charges						
	Is there a common buildings insurance policy?	Yes 😣					
	and the same of th	No 🐼					
b.		Don't know 🔕					
	If you answered yes is the cost of insurance included in your monthly/annual factor's charges?	Yes					
		No					
	Please give details of any other charges you have to pay on a regular basis for the up						
c.	areas or repair works, for example to a residents' association, or maintenance or stair None	Tuna.					
13.	Specialist works						
	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	Yes 😵					
		No 🔗					
	If you answered yes please give further details						
a.							
	Do you have any guarantees for this work?	Yes 🔕					
	Cuaranta an ara halid huu	No 🔉					
	Guarantees are held by : As far as you are aware, has any preventative work for dry rot, wet rot, or damp						
	ever been carried out to your property?	Yes 🔕 No 🕢					
	If you answered yes please give further details	140					
b.							
~ .	Do you have any guarantees for this work?	Yes 😵					
		No 🐼					
	Guarantees are held by :						



14.	Guarantees							
	Are there any warranties or guarantees for any of the following							
a.		No	Yes	Don't know	With title deeds	Lost		
(i) b.	Electrical work	8	8	Ø	8	8		
(ii) b.	Roofing	8	8		8	8		
(iii) b.	Central heating	8	8	Ø	8	8		
(iv) b.	National House Building Council (NHBC)					⊘ ⊗ ⊗		
(v) b.	Damp course	8	8	Ø	8	8		
(vi)	Any other work or installation? (for example cavity wall insulation, underpinning, indemnity policy)				×	×		
b.		ı						
_	Are there any outstanding claims under any of the guarantees listed above?		Yes No 😵					
c.	If you answered yes please give details							
15.	Boundaries							
	Are you aware has any boundary of your property been moved in the last ten years?		Yes 😵 No 🐼					
a.				Don't know				
	<u>If you answered yes</u> please give details							



16.	Notices that affect your property	
	In the past three years have you ever receievd a notice :	
a.	Advising that the owner of a neighbouring property has made a planning application?	Yes ⊗ No ⊘
b.	that affects your property in some other way?	Yes 🛭 No 🕢
c.	that requires you to perform any maintenance, repairs, or improvements to the property?	Yes ⊗ No ⊘
	If you answered yes to any of a-c above please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property	

Declaration by the seller(s) or other authorised body or person(s)

I/We confirm that the information on this form is true and correct to the best of my/our knowledge and belief.

Signatures:

James cowan

Date:





Room E101, Floor E, Marathon House, Olympic Business Centre, Kilmarnock KA2 9BE 01563 852477 kilmarnock.residential@hdg.co.uk