

HARVEY DONALDSON & GIBSON

CHARTERED SURVEYORS

Parent to HomeReportScotland.scot







- 1. Single Survey
- 2. Energy Report
- 3. Property Questionnaire



survey report on:

Property address	593 Clarkston Road, Netherlee, Glasgow, G44 3QD
Customer	Mr P Davison & Mrs C Davison
Customer address	
Prepared by	Harvey Donaldson And Gibson
Date of inspection	18th May 2023



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

Х

The ultimate holding company of Harvey Donaldson & Gibson is Countrywide plc. In Scotland, Countrywide plc also own Slater Hogg & Howison and Countrywide North. A full list of estate agents owned or under franchise to Countrywide plc is available on request. Harvey Donaldson & Gibson trades as an entirely separate company and has no financial interest whatsoever in the disposal of the property being inspected.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether
 or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information

contained in the Report and the generic Mortgage Valuation Report.²

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be

researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.


Description	The subjects comprise a two storey mid-terraced house which we understand was built CIRCA 1910. The front of the property faces approximately West.
Accommodation	Ground floor: VESTIBULE, HALL, LOUNGE, LIVING ROOM, DINING ROOM, KITCHEN AND UTILITY ROOM First floor: LANDING, THREE BEDROOMS AND BATHROOM.
Gross internal floor area (m²)	145
Neighbourhood and location	The neighbourhood is residential. The location is urban. The property is located in the Netherlee district of East Renfrewshire. The site slopes moderately. The site is close to a relatively busy road.
Age	113 years.
Weather	Dry and overcast.
Chimney stacks	The chimneys are a mixture of stone and rendered masonry. Flashing are formed in sheet lead.
Roofing including roof space	The roof is pitched and covered with slates. The roof is made up with timber rafters and purlins (horizontal beams). There is a parapet front bay feature with a concealed walhead gutter. There is a mono pitched slated roof over the rear projection.
Rainwater fittings	The rainwater fittings are iron/steel.

Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The walls are of solid sandstone and roughcast brick construction, lathed and plastered internally.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	The windows are a mixture of original and replacement fittings. The remaining original fittings are single glazed sash and casement timber framed units with some secondary glazing and the replacement are modern , double glazed upvc, sash and casement (CR SMITH) units to the front elevation and older upvc double glazed units with hopper type openings. The front door is a metal units and the rear door a more modern upvc double glazed unit.
	Eaves timbers are timber boarded.
External decorations	The external joinery is painted.
Conservatories / porches	None.
Communal areas	None.
Garages and permanent outbuildings	The garage is timber framed. The garage is clad with asbestos cement.
Outside areas and boundaries	There are garden grounds to the front and rear of the property. They are suitably bounded by timber fencing and brick retaining walls. There concrete slabs, cast concrete and stone and brick retaining walls.
Ceilings	Visually inspected from floor level.
	The ceilings are lath & plaster.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	The internal walls are of masonry construction plastered on hard.

Floors including sub floors	The floors are of a suspended timber type with timber joists and covered with floorboards. The rear projection floor is of solid concrete construction.
Internal joinery and kitchen fittings	The internal doors are timber panelled with some part glazed doors. The skirting boards and door surrounds are timber. The staircase is timber. The kitchen fittings are of a modern contemporary design and consist of a range of floor and wall mounted units.
Chimney breasts and fireplaces	There is fireplace in the lounge.
Internal decorations	Visually inspected. The ceilings are painted. The walls are papered and painted.
Cellars	None.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. Mains electricity is installed. The meter and consumer unit are located in the hall. The system appears to be of a modern 13 amp type and design. The switch and socket outlets are plastic and the wiring is sheathed with PVC, where visible.
Gas	Gas is supplied from the mains.
Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation. No tests whatsoever were carried out to the system or appliances. Water is supplied from the mains. The rising main is not visible. The distribution pipes are a mixture of copper and plastic. The bathroom contains a bath, seperate shower cubicle with electric shower, basin and w.c.
Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances. The property is heated by a gas fired boiler. The boiler is a combination boiler also providing hot water direct to taps. Heating to the rooms is provided by water filled radiators.

Drainage	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.
	The property is believed to be connected to mains drainage.
Fire, smoke and burglar alarms	Scottish government regulations came into effect on 1st February 2022 which requires each property to have linked smoke and heat detectors and if gas/carbon burning appliances are present then a carbon monoxide alarm fitted. Purchasers should satisfy themselves with regards to compliance.
Any additional limits to inspection	It was over cast and dry at the time of the inspection. Preceding the inspection the weather was dry. The property was occupied. The property was furnished. The floors were covered with fixed coverings. In this context the tiled floor finishes are considered as a covering to the structure of the floor. In this context the laminate board floor finishes are considered as a covering to the structure of the floor. We were unable to gain access to the sub floor area as there is no apparent means of access. Stored goods restricted the inspection. The insulation at ceiling level prevented inspection of the ceiling and joists in the roof space.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1) Chimney pots
- 2) Coping stone
- 3) Chimney head
- 4 Flashing
- 5) Ridge ventilation
- 6 Ridge board
- 7) Slates / tiles
- 8 Valley guttering
- 9) Dormer projection
- 10 Dormer flashing
- 11) Dormer cheeks
- (12) Sarking
- (13) Roof felt
- (14) Trusses
- 15) Collar
- (16) Insulation
- (17) Parapet gutter
- (18) Eaves guttering
- 19) Rainwater downpipe
- 20) Verge boards /skews
- 21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- 24) Chimney breast
- 25) Window pointing
- 6) Window sills
- 27) Rendering
- (28) Brickwork / pointing
- 29) Bay window projection
- 30 Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- 33 Damp proof course
- 34) Base course
- 35) Foundations
- 36) Solum
- Floor joists
- 38) Floorboards
- 39) Water tank
- 40 Hot water tank

2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category	1
Notes	All buildings move daily and seasonally as a result of external factors such as gravity, temperature, moisture content and vibrations. Consequently most buildings will have minor non structural cracks related to these factors. Minor cracks can be filled during normal redecoration but often recur seasonally due to normal movement in a building. Non structural cracks of this nature will not be recorded or reported. There is evidence of movement in the form of cracking to walling. On the basis of a single visual inspection the movement appears to be longstanding in nature. The opinion provided is given within the limitations of a single visual inspection.

Dampness, rot and infestation	
Repair category	3
Notes	Rising Dampness: The walls were checked using a Protimeter moisture meter. Higher than normal damp meter readings have been recorded to walls internally at ground floor level at the rear wall of the living room. The pattern of the readings suggests that the damp proof course is not fully effective.

Chimney stacks	
Repair category	2
Notes	The chimneys are old and worn and some patch repairs have been carried out to pointing and flashings have been painted and filled in places. Ongoing attention should be anticipated.

Roofing including roof space	
Repair category	2
Notes	The roof covering is old and entering the latter stages of its performance life. A number of cracked/chipped, missing and broken slates were noted. Some areas have been patch repaired. An overhaul is required and ongoing and regular attention will be required until full recovering is carried out. The parapet wall head feature will require regular and careful maintenance. Corroded slate nails were noted and evidence of past occasional leakage to timber sarking boards.

Rainwater fittings	
Repair category	2
Notes	It was not raining at the time of the inspection and it is therefore not possible to confirm that all joints are completely water tight.
	The gutters are corroded and have flaking paintwork.

Main walls	
Repair category	1
Notes	The sandstone is weathered and eroded in places but this is considered commensurate with the age and type of property inspected. The walls are in average condition allowing for normal weathering. Some open pointing was noted to the front elevation.
	There is evidence of movement in the form of cracking to walling. On the basis of a single visual inspection the movement appears to be longstanding in nature. The opinion provided is given within the limitations of a single visual inspection.

Windows, external doors and joinery	
Repair category	2
Notes	The windows and doors are in reasonable condition consistent with their age. However, some units have failed with condensation noted between the glazing. These require renewal. The older single galzed widows require to be overhauled and repaired as found necessary. The eaves are is fair condition for age and type.

External decorations	
Repair category	1
Notes	The external decorations are in reasonable condition but are beginning to deteriorate.

Conservatories/porches	
Repair category	-
Notes	Not applicable.

Communal areas	
Repair category	-
Notes	Not applicable.

Garages and permanent outbuildings	
Repair category	2
Notes	The garage is in poor condition. Timber decay was noted and cracked glazing was noted. The asbestos cement roof sheeting must be considered to be near the end of its performance life. Replacement costs can be high.

Outside areas and boundaries	
Repair category	2
Notes	The outside areas and boundaries are in need of some attention . The rear side retaining brick wall is cracked and leaning out of plumb.

Ceilings	
Repair category	1
Notes	The ceilings are cracked but reasonably sound allowing for their age. However, given the age of ceilings some loose and defective plaster may be found on redecoration which will require to be replaced.

Internal walls	
Repair category	1
Notes	The internal walls are satisfactory.
	SEE DAMPNESS SECTION

Floors including sub-floors	
Repair category	1
Notes	The floors where visible are generally satisfactory allowing for its age and normal wear.

Internal joinery and kitchen fittings	
Repair category	1
Notes	The internal joinery and kitchen units are satisfactory. The skirting boards and door surrounds are satisfactory. The staircase is satisfactory.

Chimney breasts and fireplaces	
Repair category	1
Notes	The adequacy of the flue was not tested.

Internal decorations	
Repair category	-
Notes	The internal decorations are reasonable but marked in places from wear and tear.

Cellars	
Repair category	-
Notes	Not applicable.

Electricity			
Repair category	3		
Notes	It is recommended good practice that all electrical installations should be checked periodically, approximately every ten years or when a property changes hands. This should be regarded as a routine safety and maintenance check. The installation appears dated. A number of sockets are surface mounted on skirting boards which is contrary to current regulations. The consumer unit does not incorporate a modern residual circuit breaker. The consumer unit has re-wirable fuses.		

Gas	
Repair category	1
Notes	The gas installation appears to be generally commensurate with the age of the installation. The gas meter and supply should be checked on an annual basis.

Water, plumbing and bathroom fittings		
Repair category	1	
Notes	The plumbing installation appeared satisfactory. The sanitary fittings appeared satisfactory.	

Heating and hot water		
Repair category	1	
Notes	The system was running at the time of the inspection and appeared serviceable. It is recommended good practice that gas boilers are serviced on an annual basis by an appropriately qualified person. The boiler's service history should be checked by referring to the service records. If there is no record of a recent service, the boiler should be checked by an appropriately qualified person.	

Drainage	
Repair category	1
Notes The above ground drainage pipes appeared satisfactory.	

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	3
Chimney stacks	2
Roofing including roof space	2
Rainwater fittings	2
Main walls	1
Windows, external doors and joinery	2
External decorations	1
Conservatories/porches	-
Communal areas	-
Garages and permanent outbuildings	2
Outside areas and boundaries	2
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	-
Cellars	-
Electricity	3
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground floor
2. Are there three steps or fewer to a main entrance door of the property?	Yes No X
3. Is there a lift to the main entrance door of the property?	Yes No X
4. Are all door openings greater than 750mm?	Yes No X
5. Is there a toilet on the same level as the living room and kitchen?	Yes No X
6. Is there a toilet on the same level as a bedroom?	Yes X No
7. Are all rooms on the same level with no internal steps or stairs?	Yes No X
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

The legal adviser should check and confirm whether the property is within a conservation area. The documentation from the Local Authority confirming consents for replacement windows should be exhibited.

Access to the rear of the property is via a shared private road. The legal adviser should confirm what rights and responsibilities are attached to this.

The tenure is understood to be outright ownership The management and service charge details have not been inspected and it is assumed it does not contain onerous provisions which would adversely affect valuation.

In line with our normal practice, it is specifically assumed that the property and its value are unaffected by any matters which would or should be revealed to a competent Completing Solicitor by a local search and replies to the usual enquiries, or by any statutory notice and planning proposal.

The property is situated in an area of past mining activity. Legal adviser(s) to obtain a mining report from the coal authority and ensure that the requirements of the Coal Mining Subsidence Acts have been complied with. Access to the property is via a shared road. The legal adviser should confirm what rights and responsibilities are attached to this.

Estimated reinstatement cost for insurance purposes
£473,000 (Four hundred and seventy three thousand pounds).

Valuation and market comments

In its present condition the opinion of valuation for the Outright Ownership interest with vacant possession on 18th MAY 2023 is £400,000 (Four hundred thousand pounds sterling).

Signed	Security Print Code [496371 = 9107]O Electronically signed		
Report author	Andrew G Scrimgeour		
Company name	Harvey Donaldson And Gibson		

Address	Suite 3/7 Standard Buildings, 94 Hope Street, Glasgow, G2 6PH
Date of report	24th May 2023



		lasgow, G44 3QD	
	_	Purpose built maiso	onette Converted maisonette Flat over non-residential use Other (specify in General Remarks)
		X Mid terrace Low rise block	End terrace Other (specify in General Remarks)
	was built for	the public sector,	Yes X No
/ Floor(s) on which locate	ed	No. of floors in block	
Construction ₁₉₁₀		NO. OI UIIIS III DIOCA	·
Leasehold Grou	nd rent £	Unexpire	ed years
	Bedroom(s) WC(s)	1 Kitchen(s) 1 Other (Specify in	General remarks)
luding garages and ou	tbuildings)	145 m² (Internal)	170 m² (External)
greater than 40%) 🛛 Y	es No		
Dutbuildings			
Double garage X Yes No	Parki	ing space	No garage / garage space / parking space
js:			
ildings.			
	Mr P Davison & Mrs Co 18th May 2023 X House B Purpose built flat Co Detached Shack to back He lieve that the property vilitary, police? Y Floor(s) on which locate Construction 1910 Leasehold Ground Grou	Mr P Davison & Mrs C Davison 18th May 2023 X House	No. of floors in block Semiderated Semiderated No. of floors in block No. of units in block Semiderated No. of units in block Semiderated No. of units in block No. of units in bl

Construction							
Walls	X Brick	Stone	Concrete	Timber frame	Other	(specify in Gen	eral Remarks)
Roof	Tile	X Slate	Asphalt	Felt	Other	(specify in Gen	eral Remarks)
Special Risks							
Has the property s	suffered struc	tural moveme	nt?			Yes	X No
If Yes, is this rece						Yes	No
Is there evidence, immediate vicinity	history, or re		oate subsidence	, heave, landslip o	or flood in the		X No
If Yes to any of the	e above, prov	ide details in	General Remark	ss.			
Samina Cannon	tion						
Service Connec		16 :			<u>.</u>	41 4	11 4
Based on visual in of the supply in Go	ispection only eneral Remai	v. If any servic ks.	es appear to be	non-mains, please	e comment o	n the type ar	nd location
Drainage	X Mains	Private	None	Water	X Mains	Private	None
Electricity	X Mains	Private	None	Gas	X Mains	Private	None
Central Heating	X Yes	Partial	None				
Brief description o	f Central Hea	iting:					
Heating fuel: Ga		_					
Heating type: Ra							
Site							
Apparent legal iss	ues to be ver	ified by the co	nveyancer. Plea	ase provide a brief	description i	n General Re	emarks.
Rights of way	Shared driv	es / access	Garage or other	amenities on separate	site Shar	ed service conn	ections
Ill-defined boundar	ies	Agricult	ural land included w	th property	Othe	r (specify in Ger	neral Remarks)
Location							
X Residential suburb	Re	sidential within to	wn / city Mixe	ed residential / commer	rcial Main	ly commercial	
Commuter village	Re	mote village	Isola	ated rural property	Othe	r (specify in Ger	neral Remarks)
Planning Issues	5						
Has the property been extended / converted / altered? X Yes No							
If Yes provide details in General Remarks.							
Roads							
X Made up road	Unmade roa	d Partly	completed new road	Pedestrian a	ccess only	Adopted	Unadopted

Canara	Damarka
CINICIPAL	l Remarks

There is a utility room.

The general condition of the property appears consistent with its age and type of construction. There are some items requiring attention, however these are of a relatively minor nature and capable of remedy by routine maintenance.

The property has been affected by structural movement in the past. This appears to be of a longstanding nature, and the risk of further movement is remote.

The legal adviser should check and confirm whether the property is within a conservation area. The documentation from the Local Authority confirming consents for replacement windows should be exhibited.

Access to the rear of the property is via a shared private road. The legal adviser should confirm what rights and responsibilities are attached to this

The property is situated in an area of past mining activity. The conveyancer should obtain a mining report from The Coal Authority to provide information as to historical and future mining activity and whether the property has been the subject of any compensation claims, ensuring that the property is not adversely affected. The valuation assumes the content will reveal nothing adverse.

	Essential	Repa	irs
--	------------------	------	-----

Dampness in the living room walling requires to be further investigated and upgrading of	the electric is required
Damphess in the living room walling requires to be further investigated and appraising or	the electric is required.
Estimated cost of essential repairs £ - Retention recommended? Yes X	No Amount £ -

Comment on Mortgageability				
The property affords adeq	uate security for loan purposes based on the valuation figure.			
Valuations				
Buy To Let Cases What is the reasonable rangmonth Short Assured Tenan	n of essential repairs lue rebuilding, site clearance, professional fees, ancillary charges plus VAT) ?? ge of monthly rental income for the property assuming a letting on a 6	£ 400,000 £		
Signed Surveyor's name Professional qualifications Company name Address Telephone Fax Report date	Security Print Code [496371 = 9107]O Electronically signed by:- Andrew G Scrimgeour Bsc MRICS Harvey Donaldson And Gibson Suite 3/7 Standard Buildings, 94 Hope Street, Glasgow, G2 6PH 0141 204 0808 0203 880 9193 24th May 2023			

Energy Performance Certificate (EPC)

Dwellings

Scotland

593 CLARKSTON ROAD, NETHERLEE, GLASGOW, G44 3QD

Dwelling type:Mid-terrace houseDate of assessment:18 May 2023Date of certificate:18 May 2023Total floor area:145 m²

Primary Energy Indicator: 257 kWh/m²/year

Reference number: 6400-2187-0722-8094-1573
Type of assessment: RdSAP, existing dwelling

Approved Organisation: Elmhurst

Main heating and fuel: Boiler and radiators, mains


gas

You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£9,552	See your recommendations
Over 3 years you could save*	£3,189	report for more information

^{*} based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (63)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (55)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Internal or external wall insulation	£4,000 - £14,000	£1776.00
2 Floor insulation (suspended floor)	£800 - £1,200	£405.00
3 Low energy lighting	£45	£132.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Solid brick, as built, no insulation (assumed)	***	$\star\star$
	Sandstone or limestone, as built, no insulation (assumed)	***	***
Roof	Pitched, 200 mm loft insulation	****	★★★ ☆
	Pitched, no insulation (assumed)	****	\bigstar \updownarrow \updownarrow \updownarrow \updownarrow
Floor	Suspended, no insulation (assumed)	_	_
	Solid, no insulation (assumed)	_	_
Windows	Partial double glazing	***	★★★☆☆
Main heating	Boiler and radiators, mains gas	****	★★★ ☆
Main heating controls	Programmer, TRVs and bypass	***	***
Secondary heating	None	_	_
Hot water	From main system	****	***☆
Lighting	Low energy lighting in 72% of fixed outlets	****	****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 45 kg $CO_2/m^2/yr$.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 6.6 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 3.2 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£8,019 over 3 years	£5,232 over 3 years	
Hot water	£813 over 3 years	£564 over 3 years	You could
Lighting	£720 over 3 years	£567 over 3 years	save £3,189
Totals	£9,552	£6,363	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures		Indicative cost	Typical saving	Rating after improvement	
		indicative cost	per year	Energy	Environment
1	Internal or external wall insulation	£4,000 - £14,000	£592	C 69	D 64
2	Floor insulation (suspended floor)	£800 - £1,200	£135	C 71	D 66
3	Low energy lighting for all fixed outlets	£45	£44	C 71	D 66
4	Upgrade heating controls	£350 - £450	£115	C 73	D 68
5	Solar water heating	£4,000 - £6,000	£84	C 74	C 69
6	Replace single glazed windows with low- E double glazed windows	£3,300 - £6,500	£93	C 75	C 71
7	Solar photovoltaic panels, 2.5 kWp	£3,500 - £5,500	£602	B 82	C 77

Choosing the right improvement package





About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Internal or external wall insulation

Internal or external wall insulation involves adding a layer of insulation to either the inside or the outside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. External solid wall insulation is the application of an insulant and a weather-protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide long-lasting weather protection. Further information can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). It should be noted that a building warrant is required for the installation of external wall insulation. Planning permission may also be required and that building regulations apply to external insulation so it is best to check with your local authority on both issues.

2 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

3 Low energy lighting

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting).

4 Heating controls (room thermostat)

The heating system should have a room thermostat to enable the boiler to switch off when no heat is required. A competent heating engineer should be asked to do this work. Insist that the thermostat switches off the boiler as well as the pump and that the thermostatic radiator valve is removed from any radiator in the same room as the thermostat. Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

5 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

6 Double glazed windows

Double glazing is the term given to a system where two panes of glass are made up into a sealed unit. Replacing existing single-glazed windows with double-glazed windows will improve comfort in the home by reducing draughts and cold spots near windows. Double-glazed windows may also reduce noise, improve security and combat problems with condensation. Building regulations apply to this work and planning permission may also be required, so it is best to check with your local authority on what standards need to be met. A building warrant is not required if the windows comply with the current requirements.

7 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	21,034	(1,082)	N/A	(5,114)
Water heating (kWh per year)	2,316			

Addendum

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Andrew Scrimgeour

Assessor membership number: EES/016076

Company name/trading name: Harvey Donaldson & Gibson Chartered Surveyors Suite 3/7 Standard Buildings 94 Hope Street

Glasgow G2 6PH

Phone number: 0141 2040808

Email address: frances.wilson@hdg.co.uk

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greeners cotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT





Property Address	593 Clarkston Rd, G44 3QD
Vendor(s)	Mr peter davison
Completion Date of Property Questionnaire	10/05/2023 19:36
System Ref:	QV049516





Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1.	Length of ownership				
	How long have you owned the property? 22 years				
2.	Council Tax				
۷.	Which Council Tax band is your property in?				
		- 🐼			
•		6 <u>&</u> H	×		
3.	Parking				
	What are the arrangements for parking at your property? Please tick all that apply?				
	Garage ✓ Allocated parking space ⊗	Drivewa	_		
	Shared parking ⊗ On street ✓	Resident perm	it 😵		
	Metered parking 🔕 Other (please specify):				
4.	Conservation area				
	Is your property in a designated Conservation Area (that is an area of	Ye	es 😵		
	special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	N	o 🐼		
	The state of the s	Don't kno	w 🗸		
5.	Listed buildings				
	Is your property a Listed Building, or contained within one (that is a building	Ye	es 😵		
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?		es 😵 o 🧭		
6.					
6.	recognised and approved as being of special architectural or historical interest)? Alterations/additions/extensions During your time in the property, have you carried out any structural alterations, additions or	N	0 🕢		
6. a.	recognised and approved as being of special architectural or historical interest)? Alterations/additions/extensions	N Ye	o 🔗		
	recognised and approved as being of special architectural or historical interest)? Alterations/additions/extensions During your time in the property, have you carried out any structural alterations, additions or	N Ye	0 🕢		
	recognised and approved as being of special architectural or historical interest)? Alterations/additions/extensions During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	N Ye	o 🔗		
a.	recognised and approved as being of special architectural or historical interest)? Alterations/additions/extensions During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	Y ₀	o 🔗		
a.	recognised and approved as being of special architectural or historical interest)? Alterations/additions/extensions During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)? If you have answered yes, please describe below the changes which you have made:	Ye N	0		
a. (i)	Alterations/additions/extensions During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)? If you have answered yes, please describe below the changes which you have made: Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	You N	0		
a. (i) (ii)	Alterations/additions/extensions During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)? If you have answered yes, please describe below the changes which you have made: Did you obtain planning permission, building warrant, completion certificate and other consents for this work? If you have answered yes, the relevant documents will be needed by the purchaser and you solicitor as soon as possible for checking. If you do not have the documents yourself, please not	You No	0		
a. (i)	Alterations/additions/extensions During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)? If you have answered yes, please describe below the changes which you have made: Did you obtain planning permission, building warrant, completion certificate and other consents for this work? If you have answered yes, the relevant documents will be needed by the purchaser and you seem to the purc	You No	0		



6.	Alterations/additions/extensions			
	Have you had replacement windows, doors, patio doors or double glazing installed in your	Yes 🤡		
b.	property? If you have answered yes, please answer the three questions below	No 😵		
	Were the replacements the same shape and type as the ones you	Yes 🤡		
(i)	replaced?	No 😵		
/::\	Did the work involve any changes to the window or door openings?	Yes 😵		
(ii)		No 🗸		
(iii)	Please describe the changes made to the windows doors, or patio doors (with approximate data completed): Sash and case double glazed units fitted to front of property 2022. Please give any guarantees which you received for this work to your solicitor or estate agent	tes when the work was		
7.	Central heating			
	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main	Yes 🤡		
a.	rooms of the property —	No 😵		
	the main living room, the bedroom(s), the hall and the bathroom).	Partial 🚫		
	If you have answered yes or partial – what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air)			
	gas If you have answered yes, please answer the three questions below			
(i)	When was your central heating system or partial central heating installed?	2011		
	Do you have a maintenance contract for the central heating system?	Yes 😵		
, <u>.</u>		No 🗸		
(ii)	If you answered yes please give details of the company with whom you have a maintenance contract			
(iii)	When was your maintenance contract last renewed? (Please provide the month and year)			
8.	Energy Performance Certificate			
	Does your property have an Energy Performance Certificate which is less	Yes 🔇		
	than 10 years old?	No 🕢		
9.	Issues that may have affected your property			
	Has there been any storm, flood, fire, or other structural damage to your	Yes 🗸		
а.	property while you have owned it?	No 😵		
	If you have answered yes is the damage the subject of any outstanding	Yes 😵		
	insurance claim?	No 🧭		
	Are you aware of the existence of asbestos in your property?	Yes 😵		
b.		No 🕢		
	If you have answered yes please give details:			



10.	Services				
	Please tick which services are connected to your property and give details of the supplier				
	Service	Connected	Suppl	ier	
	Gas or liquid petroleum gas		scottish p	oower	
	Water mains or private water supply		scottish v	water	
a.	Electricity		scottish p	oower	
	Mains drainage		scottish v	water	
	Telephone		virgir	า	
	Cable TV or satellite		virgir	า	
	Broadband		virgii	า	
h	Is there a septic tank at your property?			Yes 😵	
b.	If you have answered yes please answered	ver the questions b	elow	No 🤡	
	Do you have appropriate consents for the	ne discharge of you	r septic tank?	Yes 😵	
(i)				No 😵	
				Don't know 🚫	
	Do you have a maintenance contract fo	r your septic tank?		Yes 😵	
/::\				No 😵	
(ii)	If you answered yes please give details of the company with whom you have a maintenance contract				
11.	Responsibilities for shared or comme	on areas			
	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as repair of a shared drive, private road, boundary, or garden area?			Yes 🔕	
a.				No 🕢	
				No ✓ Don't know	
	If you answered yes please give details				
				Don't know 😣	
	Are you aware of any responsibility to c				
				Don't know 😣	
b.	Are you aware of any responsibility to c			Don't know Yes	
b.	Are you aware of any responsibility to c			Don't know Yes No No	
b.	Are you aware of any responsibility to c maintenance of the roof, common stairs			Don't know Yes No No	
	Are you aware of any responsibility to comaintenance of the roof, common stairs If you answered yes please give details No Has there been any major repair or repl	vell, or other common	on areas?	Don't know Yes No No	
b. c.	Are you aware of any responsibility to c maintenance of the roof, common stairv If you answered yes please give details No	vell, or other common	on areas?	Yes No Don't know	
	Are you aware of any responsibility to commaintenance of the roof, common stairs If you answered yes please give details No Has there been any major repair or repl during the time you have owned the buil	acement of any par lding?	t of the roof property, for	Don't know Yes No Don't know Yes Yes Yes	
C.	Are you aware of any responsibility to comaintenance of the roof, common stairs If you answered yes please give details No Has there been any major repair or repl during the time you have owned the bui	acement of any par lding?	t of the roof property, for	Pon't know S Yes No Don't know S Yes No Ves No Ve	
	Are you aware of any responsibility to commaintenance of the roof, common stairs If you answered yes please give details No Has there been any major repair or repl during the time you have owned the buil	acement of any par lding?	t of the roof property, for	Yes & No Don't know & Yes No Ves No Ves No Ves Xes No Ves Xes Xes	



11.	Responsibilities for shared or common areas	
	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin, or to maintain their boundaries?	Yes 😵
e.	property, for example to put out their rubbish biri, or to maintain their boundaries?	No 🤡
C.	<u>If you answered yes</u> please give details	
		,
	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately owned.)	Yes 😵
f.		No 🔗
	<u>If you answered yes</u> please give details	
12.	Charges associated with your property	
12.	Is there a factor or property manager for your property?	Yes 😵
	is there a factor or property manager for your property:	Yes No 🕢
a.	If you answered yes please provide name and address and give details relating to deposits held	
		and charges
	Is there a common buildings insurance policy?	Yes 😣
	and the same of th	No 🐼
b.		Don't know 🔕
	If you answered yes is the cost of insurance included in your monthly/annual factor's charges?	Yes
		No
	Please give details of any other charges you have to pay on a regular basis for the up	
C.	areas or repair works, for example to a residents' association, or maintenance or stair none	Tuna.
13.	Specialist works	
	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	Yes 😵
		No 🔗
	If you answered yes please give further details	
a.		
	Do you have any guarantees for this work?	Yes 🔕
	Consente an analysis of	No 🐼
	Guarantees are held by : As far as you are aware, has any preventative work for dry rot, wet rot, or damp	
	ever been carried out to your property?	Yes 🔕 No 🕢
	If you answered yes please give further details	140
b.		
~ .	Do you have any guarantees for this work?	Yes 🔕
		No 🐼
	Guarantees are held by :	



14.	Guarantees						
	Are there any warranties or guarantees for any of the following						
a.		No	Yes	Don't know	With title deeds	Lost	
(i) b.	Electrical work	Ø	8	8	8	8	
(ii) b.	Roofing	Ø	8	8	8	8	
(iii) b.	Central heating	Ø	8	8	8	8	
(iv) b.	National House Building Council (NHBC)	Ø	8	8	8	8	
(v) b.	Damp course	Ø	8	8	8	8	
(vi)	Any other work or installation? (for example cavity wall insulation, underpinning, indemnity policy)		×	×	×	×	
b.		ı					
	Are there any outstanding claims under any of the guarantees listed above?			Yes 😵 No 🐼			
c.	<u>If you answered yes</u> please give details						
15.	Boundaries						
	Are you aware has any boundary of your property been moved ten years?	in the I	ast			'es 😵 No 🧭	
a.				Do	n't kno		
	If you answered yes please give details						



16.	Notices that affect your property		
	In the past three years have you ever receievd a notice :		
a.	Advising that the owner of a neighbouring property has made a planning application?	Yes ⊗ No ⊘	
b.	that affects your property in some other way?	Yes No 🥥	
c.	that requires you to perform any maintenance, repairs, or improvements to the property?	Yes ⊗ No ⊘	
	If you answered yes to any of a-c above please give the notices to your so agent, including any notices which arrive at any time before the date of entry of your property		

Declaration by the seller(s) or other authorised body or person(s)

I/We confirm that the information on this form is true and correct to the best of my/our knowledge and belief.

Signatures:

p davison

ce davison

Date:





3/7 Standard Buildings, 94 Hope Street, Glasgow, G2 6PH 0141 2040808 glasgow.residential@hdg.co.uk